

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Tuesday, February 12, 2019 1:10 PM
To: 'DeAnn Grant'; Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Initial) Screwdriver 24 Federal Com #002H (30-015-42914) 01-23-2019

Screwdriver 24 Federal Com #002H (30-015-42914) 01-23-2019

All,
The OCD tracking number for this release event is **2RP-5233**.
Thank you,

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Thursday, February 7, 2019 8:49 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Tucker, Shelly <stucker@blm.gov>; dmckinne@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Initial) Screwdriver 24 Federal Com #002H (30-015-42914) 01-23-2019

Mr. Bratcher/Mr. Amos,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated wet soil depth and depth of fluid in the liner. No gravel was present in this lined facility as it is a Falcon Liner. The unrecovered volume is the total amount in the pasture and the residue left behind on the liner and equipment which will be cleaned by pressure wash. The spreadsheet will calculate the total volume lost. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

