

## Hamlet, Robert, EMNRD

---

**From:** Rebecca Haskell <RHaskell@concho.com>  
**Sent:** Wednesday, March 6, 2019 3:25 PM  
**To:** Bratcher, Mike, EMNRD  
**Cc:** Jim Amos (jamos@blm.gov); Deborah McKinney; Weaver, Crystal (caweaver@blm.gov); Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Dakota Neel; Sheldon Hitchcock; DeAnn Grant; Ike Tavaréz; Rebecca Haskell; Jennifer Knowlton  
**Subject:** [EXT] (Extension Request) McIntyre B #10 Tank Battery 12-06-2018

Mr. Bratcher,

Under the new spill rule a work plan or closure report is due for the above release on 3/6/19. COG is currently working on scheduling a crew to conduct this remediation at risk. COG is requesting a three month extension until June 6, 2019 in order to complete the remediation work and prepare a closure report.

Thank You,

Becky Haskell  
Senior HSE Coordinator  
COG Operating LLC  
600 W Illinois Avenue | Midland, TX 79701  
Direct: 432-818-2372 | Main: 432.683.7443  
Cell: 432-556-5130  
[rhaskell@concho.com](mailto:rhaskell@concho.com)



CONFIDENTIALITY NOTICE: The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

---

**From:** Bratcher, Mike, EMNRD [mailto:mike.bratcher@state.nm.us]  
**Sent:** Tuesday, January 08, 2019 1:36 PM  
**To:** DeAnn Grant <agrants@concho.com>; Tucker, Shelly <stucker@blm.gov>  
**Cc:** jamos@blm.gov; Ike Tavaréz <itavaréz@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>  
**Subject:** [External] RE: (C-141 Initial) McIntyre B #10 Tank Battery 12-06-2018

\*\*\*\* External email. Use caution. \*\*\*\*

RE: COG \* McIntyre B 10 Tank Battery \* DOR: 12/6/2018

All,

The OCD tracking number for this release event is **2RP-5127**.

Thank you,

Mike Bratcher  
NMOCD District 2  
811 South First Street  
Artesia, NM 88210  
575-748-1283 Ext 108

---

**From:** DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>  
**Sent:** Tuesday, December 18, 2018 7:34 AM  
**To:** Bratcher, Mike, EMNRD <[mike.bratcher@state.nm.us](mailto:mike.bratcher@state.nm.us)>; Tucker, Shelly <[stucker@blm.gov](mailto:stucker@blm.gov)>  
**Cc:** [jamos@blm.gov](mailto:jamos@blm.gov); Ike Tavaréz <[itavarez@concho.com](mailto:itavarez@concho.com)>; Robert McNeill <[RMcNeill@concho.com](mailto:RMcNeill@concho.com)>; Sheldon Hitchcock <[SLHitchcock@concho.com](mailto:SLHitchcock@concho.com)>; Dakota Neel <[DNeel2@concho.com](mailto:DNeel2@concho.com)>; Rebecca Haskell <[RHaskell@concho.com](mailto:RHaskell@concho.com)>; DeAnn Grant <[agrant@concho.com](mailto:agrant@concho.com)>  
**Subject:** [EXT] (C-141 Initial) McIntyre B #10 Tank Battery 12-06-2018

Mr. Bratcher/Ms. Tucker,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

***DeAnn Grant***

HSE Administrative Assistant

[agrant@concho.com](mailto:agrant@concho.com)

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

