

Venegas, Victoria, EMNRD

From: DeAnn Grant <agrant@concho.com>
Sent: Thursday, June 6, 2019 12:32 PM
To: Bratcher, Mike, EMNRD; Mann, Ryan
Cc: Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD; Griswold, Jim, EMNRD; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant
Subject: [EXT] (C-141 Final) SRO State Com #064H (30-015-42130) 04-01-2019 (2RP-5359)
Attachments: (C-141 Final) SRO State Com #064H (30-015-42130) 04-01-2019 (2RP-5359).pdf

Mr. Bratcher/Mr. Mann,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



