



IMAGE COURTESY OF GOOGLE EARTH 2017

LEGEND

 RELEASE EXTENT




FIGURE 2
PRELIMINARY SOIL SAMPLE LOCATIONS
JAMES RANCH UNIT #111H
UNIT J SEC 8 T23S R31E
EDDY COUNTY, NEW MEXICO
XTO ENERGY, INC.



NOTE: REMEDIATION PERMIT NUMBER 2RP-5331