

Venegas, Victoria, EMNRD

From: DeAnn Grant <agrant@concho.com>
Sent: Thursday, June 20, 2019 9:10 AM
To: Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: Griswold, Jim, EMNRD; Hamlet, Robert, EMNRD; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell; DeAnn Grant; Venegas, Victoria, EMNRD; dmckinne@blm.gov
Subject: [EXT] (C-141 Final) Dodd Federal #11A Battery 04-17-2019 (2RP-5419)
Attachments: (C-141 Final) Dodd Federal #11A Battery 04-17-2019 (2RP-5419).pdf

Mr. Bratcher/Mr. Amos,

A final inspection has been conducted regarding the clean-up efforts made at the above mentioned lined facility. Free fluids were removed and if present the impacted gravel was removed from the liner and taken to a NMOCD approved disposal facility. The liner was inspected for damage and found to have liner integrity to contain free fluids. Please see the attached Final C-141 and picture taken during the final inspection conducted by a COG HSE representative.



Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443



