

Closure Report

Site Description

Site Name:	Sand Dunes WTF RP-(not issued yet)
Company:	Oxy USA Inc.
Legal Description:	U/L E, Section 4, T24S, R31E
County:	Eddy County, NM
GPS Coordinates:	N 32.34671 W-103.78662

Release Data

Date of Release:	5/4/19
Type of Release:	Produced water
Source of Release:	Regulator failed on back pressure valve
Volume of Release:	15 bbls
Volume Recovered:	14 bbls

Remediation Specifications

Remediation Parameters:	Removed contaminated material from within the lined battery and replaced it with clean material. The liner was inspected for integrity and found to be in great condition.	
Remediation Activities:	6/13/19 to 6/14/19	
Plan Sent to OCD:	n/a	Lined facility
OCD Approval of Plan:	n/a	n/a
Plan Sent to SLO:	n/a	Lined facility
SLO Approval of Plan:	n/a	n/a

Supporting Documentation

Initial C-141	Enclosed in this closure report
C-141, page 6	Signed and included
Site Diagram	May 2019
Pictures	Remediation pictures prior to and after backfill

Request for Closure

Based on the completion of the remediation plan, BBC International, Inc. requests closure approval from NMOCD.

Cliff Brunson, President, BBC International, Inc.

06/18/2019