

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Thursday, May 16, 2019 3:58 PM
To: DeAnn Grant; Bratcher, Mike, EMNRD; Weaver, Crystal (caweaver@blm.gov)
Cc: Hamlet, Robert, EMNRD; McKinney, Deborah; jamos@blm.gov; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Initial) Skelly Unit #973 Battery (30-015-36283) 04-16-2019

RE: (C-141 Initial) Skelly Unit #973 Battery (30-015-36283) 04-16-2019

All,
The OCD tracking number for this release event is **2RP-5418**.
Thank you,

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Wednesday, May 1, 2019 2:54 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Weaver, Crystal (caweaver@blm.gov) <caweaver@blm.gov>
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; McKinney, Deborah <dmckinne@blm.gov>; jamos@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Initial) Skelly Unit #973 Battery (30-015-36283) 04-16-2019

Mr. Bratcher/Ms. Weaver,

Please find the attached C-141 for your consideration. The calculation sheet to determine the estimated release volume is also attached. The liquid lost estimate is based on the spill dimensions and estimated depth of fluid (wet gravel depth). The spreadsheet will calculate the volume lost in the gravel, but does not include the recovered amount in the calculation. The calculated volume in the gravel and the volume recovered were added together and reported on the C-141.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

