

Candelario SWD #1 Sample Summary Table

Table 3

Sample Number on Figure 2	Sample Date	Depth (feet bgs)	Action Completed	BTEX	Benzene	GRO	DRO	MRO	Total TPH	Cl-
				ppm	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg	mg/Kg
NMOCD RRAL's for Site Ranking 20				50 mg/Kg	10 mg/Kg				100 mg/Kg	600
B1-5	3/28/2018	5	In-Situ	<0.095	<0.024	<4.8	<9.6	<48	<48	1900
B1-9	3/28/2018	9	In-Situ	<0.098	<0.025	<4.9	<10	<50	<50	450
B1-14	3/28/2018	14	In-Situ	--	--	--	--	--	--	130
B1-19	3/28/2018	19	In-Situ	<0.092	<0.023	<4.6	<9.9	<50	<50	300
B2-0	3/28/2018	Surface	Excavated	--	--	--	--	--	--	7600
B2-14	3/28/2018	14	In-Situ	<0.096	<0.024	<4.8	<10	<50	<50	920
B2-24	3/28/2018	24	In-Situ	<0.096	<0.024	<4.8	<9.7	<48	<48	180

exceeds RRAL's

excavated

"--" = Not Analyzed