

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural
Resources Department

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 24, 2018
Submit to appropriate OCD District office

Incident ID	nAB1922059305
District RP	2RP-5566
Facility ID	fAB1922058078
Application ID	pAB1922058193

Release Notification **VTATT-190729-C-1410**

Responsible Party

Responsible Party	Lucid Energy Delaware, LLC.	OGRID	372422
Contact Name	Michael Gant	Contact Telephone	575 748 4555
Contact email	Mgant@lucid-energy.com	Incident # (assigned by OCD)	nAB1922059305
Contact mailing address	201 S. 4th St., Artesia, NM 88210		

Location of Release Source

Latitude 32.248196° Longitude -103.972532°
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Juniper Pipeline release	Site Type	Natural gas gathering
Date Release Discovered	7/15/2019	API# (if applicable)	

Unit Letter	Section	Township	Range	County
F	3	24S	29E	Eddy

Surface Owner: ☐ State ☒ Federal ☐ Tribal ☐ Private (Name: Bureau of Land Management)

Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Produced Water	Volume Released (bbls) 20 bbls	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input type="checkbox"/> Condensate	Volume Released (bbls)	Volume Recovered (bbls)
<input checked="" type="checkbox"/> Natural Gas	Volume Released (Mcf) 1.5 MMcf (1500mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units) AB	Volume/Weight Recovered (provide units)

Cause of Release


The release was caused by flow erosion of the Juniper 8" polyethylene gas line. The release of gas was then ignited by nearby electrical power lines causing a fire which melted through the now exposed produced water line. The fire melted the produced water line and released approximately 20 bbls of produced water.

Incident ID	nAB1922059305
District RP	2RP-5566
Facility ID	fAB1922058078
Application ID	pAB1922058193

Was this a major release as defined by 19.15.29.7(A) NMAC? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release? This is a major release based on the volume of natural gas and produced water released.
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)? Immediate notification was provided to OCD by Kerry Egan to Rob Hamlet/ Victoria Venegas/ Mike Bratcher in District 2 on Monday 7/15/19 via email.	

Initial Response

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: Free liquids were removed by vac truck immediately following shut down of surrounding wells and power lines. The affected area has been barricaded with fencing to prevent entrance by livestock and the public.	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Michael Gant</u> Signature: <u></u> email: <u>mgant@lucid-energy.com</u>	Title: <u>Environmental Field Coordinator</u> Date: <u>7.29.19</u> Telephone: <u>314 330 7876</u>
<u>OCD Only</u> Received by: <u>Amalia Bustamante</u> Date: <u>8/8/2019</u>	