

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural  
Resources Department

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**\*\* AMENDED**

Form C-141  
Revised August 24, 2018  
Submit to appropriate OCD District office

Incident ID	NAB1922143961
District RP	2RP-5569
Facility ID	fAB1922143477
Application ID	pAB1922143677

## Release Notification CW9QD-190729-C-1410

### Responsible Party

Responsible Party	Lucid Artesia Company	OGRID	147831
Contact Name	Michael Gant	Contact Telephone	575 748 4555
Contact email	Mgant@lucid-energy.com	Incident # (assigned by OCD)	NAB1922143961
Contact mailing address	201 S. 4th St., Artesia, NM 88210		

### Location of Release Source

Latitude 32.669415° Longitude -104.495793°  
(NAD 83 in decimal degrees to 5 decimal places)

Site Name	Julie #1 Pipeline release	Site Type	Abandoned natural gas gathering
Date Release Discovered	7/17/2019	API# (if applicable)	

Unit Letter	Section	Township	Range	County
M	9	19S	25E	Eddy

Surface Owner: ☐ State ☐ Federal ☐ Tribal ☒ Private (Name: Howell Ranch)  
*\*\* BLM verified Surface Owner to be correct as Private. O.C.D. revised to show as such. AB*

### Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

<input type="checkbox"/> Crude Oil	Volume Released (bbls)	Volume Recovered (bbls)
<input type="checkbox"/> Produced Water	Volume Released (bbls)	Volume Recovered (bbls)
	Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	<input type="checkbox"/> Yes <input type="checkbox"/> No
<input checked="" type="checkbox"/> Condensate	Volume Released (bbls) <b>15 bbls</b>	Volume Recovered (bbls)
<input type="checkbox"/> Natural Gas	Volume Released (Mcf)	Volume Recovered (Mcf)
<input type="checkbox"/> Other (describe)	Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)


Cause of Release The release was caused by corrosion near a weld in the pipe which led to a pinhole leak forming on the bottom of the pipe.

Incident ID	NAB1922143961
District RP	2RP-5569
Facility ID	fAB1922143477
Application ID	pAB1922143677

Was this a major release as defined by 19.15.29.7(A) NMAC?  <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, for what reason(s) does the responsible party consider this a major release?
If YES, was immediate notice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?	

### Initial Response

*The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury*

<input checked="" type="checkbox"/> The source of the release has been stopped. <input checked="" type="checkbox"/> The impacted area has been secured to protect human health and the environment. <input checked="" type="checkbox"/> Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices. <input checked="" type="checkbox"/> All free liquids and recoverable materials have been removed and managed appropriately.	
If all the actions described above have <u>not</u> been undertaken, explain why: There were no free liquids to be recovered. The affected area has been barricaded with fencing to prevent entrance by livestock and the public.	
Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.	
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.	
Printed Name: <u>Michael Gant</u> Signature: <u></u> email: <u>mgant@lucid-energy.com</u>	Title: <u>Environmental Field Coordinator</u> Date: <u>7.29.19</u> Telephone: <u>314 330 7876</u>
<b><u>OCD Only</u></b> Received by: <u>Amalia Bustamante</u> Date: <u>8/9/2019</u>	