

Incident ID	NAB 1909136893
District RP	2RP-5324
Facility ID	fAB 1909136494
Application ID	pAB 1909136607

Remediation Plan **TLDKX-190829-C-1410**

Remediation Plan Checklist: *Each of the following items must be included in the plan.*

- ☒ Detailed description of proposed remediation technique
- ☒ Scaled sitemap with GPS coordinates showing delineation points
- ☒ Estimated volume of material to be remediated
- ☒ Closure criteria is to Table 1 specifications subject to 19.15.29.12(C)(4) NMAC
- ☒ Proposed schedule for remediation (note if remediation plan timeline is more than 90 days OCD approval is required)

Deferral Requests Only: *Each of the following items must be confirmed as part of any request for deferral of remediation.*

- ☐ Contamination must be in areas immediately under or around production equipment where remediation could cause a major facility deconstruction.
- ☐ Extents of contamination must be fully delineated.
- ☐ Contamination does not cause an imminent risk to human health, the environment, or groundwater.


I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name: Rob Kirk Title: General Manager, HSE and Compliance
 Signature:  Date: August 29, 2019
 email: rob.kirk@solarismidstream.com Telephone: 432-203-9020

OCD Only

Received by: Victoria Venegas Date: 08/29/2019

☐ Approved ☐ Approved with Attached Conditions of Approval ☒ Denied ☐ Deferral Approved

Signature:  Date: 09/06/2019

This remediation plan is DENIED for the following reason:

Missing Information. The following pages are blank:

Appendix A

Exhibit 1 – Topographic Map

Exhibit 2 – Site Diagram

Exhibit 3 – NMOSE POD Location Map

Exhibit 4 – Soil Contaminant Concentration Map

APPENDIX B – Tables

Table 1 – Soil Sample Analytical Data Summary

APPENDIX C – Photographic Documentation

Photographic Log – 03/21/2019

APPENDIX D – Certified Laboratory Reports and Chain of Custody