State of New Mexico **Oil Conservation Division** 

Incident ID	
District RP	2RP-5311
Facility ID	
Application ID	

## Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	<u>50 - 100</u> (ft bgs)	
Did this release impact groundwater or surface water?		
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	🛛 Yes 🗌 No	
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	🗌 Yes 🛛 No	
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	🗌 Yes 🛛 No	
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	🗌 Yes 🛛 No	
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	🗌 Yes 🛛 No	
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	🗌 Yes 🛛 No	
Are the lateral extents of the release within 300 feet of a wetland?	🗌 Yes 🛛 No	
Are the lateral extents of the release overlying a subsurface mine?	🗌 Yes 🛛 No	
Are the lateral extents of the release overlying an unstable area such as karst geology?	🛛 Yes 🗌 No	
Are the lateral extents of the release within a 100-year floodplain?	🗌 Yes 🛛 No	
Did the release impact areas <b>not</b> on an exploration, development, production, or storage site?	🗌 Yes 🔀 No	

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

## Characterization Report Checklist: Each of the following items must be included in the report.

- Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells. Field data
- Data table of soil contaminant concentration data
- Depth to water determination
- Determination of water sources and significant watercourses within <sup>1</sup>/<sub>2</sub>-mile of the lateral extents of the release
- $\boxtimes$  Boring or excavation logs
- Photographs including date and GIS information
- Topographic/Aerial maps
- Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Form C-141 Page 4	State of New Mexico Oil Conservation Division		Incident ID District RP Facility ID	2RP-5311
regulations all operators ar public health or the environ failed to adequately investi addition, OCD acceptance and/or regulations. Printed Name:K Signature:	formation given above is true and complete to the re required to report and/or file certain release not nment. The acceptance of a C-141 report by the C igate and remediate contamination that pose a thre of a C-141 report does not relieve the operator of Cyle Littrell	ifications and perform co DCD does not relieve the eat to groundwater, surfac responsibility for compl Title:SH&E Su Date:08/30/2019	rrective actions for rele operator of liability shi ce water, human health iance with any other fee ppervisor	eases which may endanger ould their operations have or the environment. In deral, state, or local laws
OCD Only Received by: Rober	t Hamlet	Date: 9/5/	2019	

State of New Mexico Oil Conservation Division

Incident ID	
District RP	2RP-5311
Facility ID	
Application ID	

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.				
A scaled site and sampling diagram as described in 19.15.29.11 NMAC				
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)				
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)				
Description of remediation activities				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.				
Printed Name: Kyle Littrell	Title: <u>SH&amp;E Supervisor</u>			
Signature:	Date:08/30/2019			
email:Kyle_Littrell@xtoenergy.com	Telephone: 432-221-7331			
OCD Only				
Received by: <u>Robert Hamlet</u>	Date: <u>9/5/2019</u>			
Closure approval by the OCD does not relieve the responsible party of liability should their operations have failed to adequately investigate and remediate contamination that poses a threat to groundwater, surface water, human health, or the environment nor does not relieve the responsible party of compliance with any other federal, state, or local laws and/or regulations.				
Closure Approved by:	Date: <u>9/5/2019</u>			
Printed Name: Robert Hamlet	Title: Environmental Eng. Tech. III			