

Candelario Emergency Response Sample Summary Table

Sample Number on Figure 2	Sample Date	Depth (feet bgs)	Completed Action	BTEX mg/Kg	Benzene mg/Kg	GRO mg/Kg	DRO mg/Kg	MRO mg/Kg	Total TPH mg/Kg	PID Screens	Cl- Screens (ppm)	Cl- Labs mg/Kg	Soil Type
NMOCD RRAL's for Site Ranking of 20				50 mg/Kg	10 mg/Kg				100 mg/Kg				
L1	5/3/2018	0.5	excavated	<0.217	<0.024	<4.8	<9.4	<47	<61.2	57.8	12170	850	
L2	5/3/2018	1.5	excavated	<0.216	<0.024	<4.8	<9.6	<48	<62.4	163	8014	320	
L3	4/30/2018	1	excavated	<0.221	<0.025	<4.9	41	<47	41	20	7003	6500	
L4	5/3/2018	1	excavated	<0.224	<0.025	<5.0	<9.4	<47	<61.4	119	>28700	19000	
L5	4/30/2018	1	excavated	<0.210	<0.023	5.9	69	<49	74.9	84.2	>28700	72000	
L6	5/3/2018	1	excavated	<0.219	<0.024	<4.9	<9.1	<45	<59	18.4	7.77	1600	
L7	5/3/2018	0.5	excavated	<0.213	<0.024	<4.7	15	<48	15	--	3.34	4200	
L8	5/3/2018	0.5	excavated	<0.219	<0.024	<4.9	<10	<50	<64.9	--	7.62	160	
L9	4/30/2018	0.5	excavated	<0.221	0.025	<4.9	<9.5	<47	<61.4	--	5.22	5400	
L9 West	5/3/2018	0.5	excavated	<0.225	<0.025	<5.0	<9.0	<45	<59	--	--	8000	
L10	5/1/2018	1	excavated	--	--	--	--	--	--	398	--	--	
	5/1/2018	2	excavated	<0.207	<0.023	<4.6	<9.6	<48	<62.2	14.4	--	16000	
	5/1/2018	3	excavated	<0.179	<0.020	<4.0	<9.8	<49	<62.8	4.1	--	4900	
L11	5/1/2018	1	excavated	<0.215	0.024	12	130	<47	132	230	--	27000	
	5/1/2018	1.5	excavated	--	--	--	--	--	--	--	--	--	
	5/1/2018	2	excavated	<0.143	<0.016	<3.2	23	<47	23	43.7	--	3800	
L12	5/1/2018	0.5	excavated	--	--	--	--	--	--	27.3	--	--	
	5/1/2018	1	excavated	<0.21	<0.023	<4.7	<9.6	<48	<62.3	3.1	--	16000	
	5/1/2018	2	excavated	<0.145	<0.016	<3.2	<9.0	<45	<57.2	5.1	15000	8800	
L13	5/1/2018	0.5	excavated	--	--	--	--	--	--	17.2	--	--	
	5/3/2018	1	excavated	<0.22	<0.024	<4.9	240	1000	1240	14.1	--	2000	
	5/1/2018	2	excavated	<0.180	<0.020	<4.0	<9.3	<47	<60.3	1.6	4420	5800	
L14	5/3/2018	2.5	excavated	--	--	--	--	--	--	--	--	4030	
Cell 1	8/23/2018	surface rock	hydrovaced	<0.217	<0.024	<4.8	<9.7	<48	<62.5	--	--	4500	
Cell 2	8/24/2018	surface rock	hydrovaced	<0.217	<0.024	<4.8	<9.8	<49	<63.6	--	--	2000	
Cell 3	8/24/2018	surface rock	hydrovaced	<0.212	<0.024	<4.7	<10	<50	<64.7	--	--	2200	
Cell 4	8/24/2018	surface rock	hydrovaced	<0.224	<0.025	<5.0	<10	<51	<66.0	--	--	9600	
Cell 5	8/24/2018	surface rock	hydrovaced	<0.225	<0.025	<5.0	<9.8	<49	<63.8	--	--	2300	
BG1	4/30/2018	background	--	--	--	--	--	--	--	--	--	9800	Arno-Harkey Complex (sandy)
BG2	5/3/2018	background	--	--	--	--	--	--	--	--	--	1100	Arno-Harkey Complex
Hydrovac. Water Source	8/23/2018	--	--	--	--	--	--	--	--	--	1300	--	
	8/24/2018	--	--	--	--	--	--	--	--	--	1220	--	

Hydro Excavation Data