

## Venegas, Victoria, EMNRD

---

**From:** Venegas, Victoria, EMNRD  
**Sent:** Thursday, September 19, 2019 4:47 PM  
**To:** 'Raley, Jim'; Bratcher, Mike, EMNRD; Hamlet, Robert, EMNRD  
**Cc:** Chris McKisson; Lynda Laumbach; jamos@blm.gov  
**Subject:** RE: Tucker Draw 9-4-6H Liner Inspection  
**Attachments:** (C-141 Final) TUCKER DRAW 9 4 FEDERAL COM #006H 30-015-44479\_WPX 9.19.19.pdf

### RE: Tucker Draw 9-4-6H Liner Inspection 2RP-5592

Mr. Raley,  
OCD has received your closure request and final C-141 for RE: Tucker Draw 9-4-6H Liner Inspection 2RP-5592, thank you.  
This closure is approved.  
Regards,

Victoria Venegas  
EMNRD  
OCD-District II  
Artesia  
[Victoria.Venegas@state.nm.us](mailto:Victoria.Venegas@state.nm.us)

*OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.*

---

**From:** Raley, Jim <James.Raley@wpxenergy.com>  
**Sent:** Monday, August 5, 2019 3:25 PM  
**To:** Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>  
**Cc:** Chris McKisson <cmckisson@ltenv.com>; Lynda Laumbach <llaumbach@ltenv.com>  
**Subject:** Tucker Draw 9-4-6H Liner Inspection

Mr. Bratcher  
On August 3<sup>rd</sup>, 2019 a broken sight glass allowed 20 bbls of fluids to leak into lined secondary containment at the Tucker Draw 9-4-6H, all fluids were recovered and returned to production. This incident has not yet been assigned an RP#, the C-141 has been submitted via NMOCD online portal.

This email serves as notification that this containment and liner will be inspected on August 9<sup>th</sup>, 2019 to document integrity of the liner and close this incident. Please let me know if NMOCD would like to be present for inspection.

Jim Raley | Environmental Specialist - Permian Basin  
5315 Buena Vista Dr., Carlsbad, NM 88220  
C: (575)689-7597 | [james.ralej@wpxenergy.com](mailto:james.ralej@wpxenergy.com)

