Form C-141 Page 6 State of New Mexico Oil Conservation Division

Incident ID	NAB1926640794
District RP	2RP-5622
Facility ID	
Application ID	pAB1926640548

Closure

LWOWA-190828-C-1410

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following it	tems must be included in the closure report.
A scaled site and sampling diagram as described in 19.15.29.1	1 NMAC
Photographs of the remediated site prior to backfill or photos must be notified 2 days prior to liner inspection)	of the liner integrity if applicable (Note: appropriate OCD District office
Laboratory analyses of final sampling (Note: appropriate ODC	C District office must be notified 2 days prior to final sampling)
Description of remediation activities	
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	tions. The responsible party acknowledges they must substantially nditions that existed prior to the release or their final land use in
Printed Name: DeAnn Grant	Title: HSE Administrative Assistant
Printed Name: Deann Grant Signature:	
email: agrant@concho.com	Date: <u>8/28/2019</u> Telephone: (432) 253-4513
	1
OCD Only	
Received by: Victoria Venegas	Date: 08/28/2019
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.
Printed Name: Victoria Venegas	Title: Engineering Tech. III