

<b>Location:</b>	Palmillo State #1 (30-015-23164)	
<b>Spill Date:</b>	9/7/2019	
<b>Approximate Area=</b>	369.42	ft <sup>2</sup>
<b>Average Saturation (or depth) of Spill=</b>	15.00	inches

<b>Approximate Oil %</b>	20	
<b>Average Porosity Factor=</b>	0.15	
<b>Approximate Volume Recovered=</b>	0	bbls

<b>VOLUME OF LEAK</b>		
<b>Total Oil=</b>	2.47	barrels
<b>Total Produced Water=</b>	9.87	barrels