District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

Incident ID	NAB1928436477
District RP	2RP-5655
Facility ID	
Application ID	pAB1928436018

Release Notification 4O376-190919-C-1410

Responsible Party

Responsible Party Marathon Oil Permian LLC				1	OGRID 372098			
Contact Name Isaac Castro					Contact Telephone 575-988-0561			
Contact ema	il <u>icastro@n</u>	narathonoil.com			Incident # (assigned by OCD) NAB1928436477			
Contact mailing address 4111 S. Tidwell Rd., Carlsbad, NM 88220								
Location of Release Source								
Latitude 32.21063703 Lo (NAD 83 in decimal degree					Longitude			
Site Name BLACK RIVER 15 10 STATE COM X #005H				S	Site Type Oil and gas drilling facility			
Date Release Discovered 9/5/19				1	API# (if applicable) 30-015-44070			
Unit Letter	Section	Township	Range		Coun	ty		
P	15	24S	27E	Eddy				
Surface Owner: State Federal Private (Name: Nature and Volume of Release Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)								
Crude Oi		Volume Release				Volume Recovered (bbls)		
Produced	Water	Volume Released (bbls) 7.79 bbls				Volume Recovered (bbls) <u>6 bbls</u>		
			tion of dissolved chloride in the >10,000 mg/l?		n the	⊠ Yes □ No		
Condensate Volume Released (bbls)					Volume Recovered (bbls)			
☐ Natural Gas Volume Released (Mcf)					Volume Recovered (Mcf)			
Other (describe) Volume/Weight Released (provide units			le units)		Volume/Weight Recovered (provide units)			
Cause of Release								
Operator reported an overspray from the header connection between Marathon produced water lines and San Mateo. Upon immediate inspection by the Field Operator, it was found that flange connection gave out. Approximately 7.79 barrels of produced water was released to the ground on Marathon pipe ROW. A vac truck was immediately dispatched to recover standing fluids and recovered 6 bbls.								

Form C-141 Page 2

State of New Mexico Oil Conservation Division

Incident ID	NAB1928436477
District RP	2RP-5655
Facility ID	
Application ID	pAB1928436018

Was this a major release as defined by	If YES, for what reason(s) does the responsibl This was a major release as defined by NMAC	e party consider this a major release? 2 19.15.29.7(A) based on volume of material released.				
19.15.29.7(A) NMAC?	, , , , , , , , , , , , , , , , , , ,					
☐ Yes ⊠ No						
If YES, was immediate no	otice given to the OCD? By whom? To whom?	When and by what means (phone, email, etc)?				
Initial Response						
The responsible p	party must undertake the following actions immediately unle	ess they could create a safety hazard that would result in injury				
The source of the rele	ease has been stopped.					
The impacted area has	s been secured to protect human health and the	environment.				
Released materials ha	ave been contained via the use of berms or dikes	, absorbent pads, or other containment devices.				
All free liquids and re	ecoverable materials have been removed and ma	naged appropriately.				
If all the actions described	d above have <u>not</u> been undertaken, explain why:					
D 10 15 20 9 D (4) NM	IAC 41.	1:-4:: i 1:-4-1				
has begun, please attach a	a narrative of actions to date. If remedial effor	diation immediately after discovery of a release. If remediation its have been successfully completed or if the release occurred attach all information needed for closure evaluation.				
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.						
Printed Name: <u>Isaac</u>	c Castro Title	e: <u>Environmental Professional</u>				
Signature:	e Castro	Date:9/19/19				
email: <u>icastro@maratho</u>	onoil.comT	Telephone:575-988-0561				
OCD Only						
Received by:Amalia B	Bustamante Da	te:10/11/2019				