

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Friday, October 11, 2019 1:43 PM
To: 'Barnhill, Amy D.'; Hamlet, Robert, EMNRD
Cc: Bratcher, Mike, EMNRD; jamos@blm.gov
Subject: RE: SND 12 01 003 #003 - D&C OBM Spill 06/19/2019
Attachments: 4. (C-141 Final) SND 12 01 003 #003H DC OBM Spill 06192019 10.11.19.pdf

SND 12 01 003 #003 - D&C OBM Spill 06/19/2019 2RP-5531

Ms. Barnhill,
OCD has received your closure request and final C-141 for SND 12 01 003 #003 - D&C OBM Spill 06/19/2019 2RP-5531.
This closure is approved.
Regards,

Victoria Venegas
EMNRD
OCD-District II
Artesia NM
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: Barnhill, Amy D. <ABarnhill@chevron.com>
Sent: Thursday, July 11, 2019 10:10 AM
To: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>
Cc: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>
Subject: [EXT] FW: SND 12 01 003 #003 - D&C OBM Spill 06/19/2019

Hello,

This was originally submitted on 6-28-19. Was it ever given an RP number? I cannot find it online.

Thank you,
Amy Barnhill
Waste and Water Specialist
MCBU
Office: 432-687-7108
Cell: 432-940-8524
E-Mail: ABarnhill@chevron.com
#OurEnvironmentMatters

From: DeLeon, Josepha

Sent: Friday, June 28, 2019 11:32 AM

To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; James Amos <jamos@blm.gov>; Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>

Cc: Vance, Richard <RVUD@chevron.com>; Reed, Dusty <DUSR@chevron.com>; Faulkner, Rick <Rick.Faulkner@chevron.com>; Barnhill, Amy D. <ABarnhill@chevron.com>

Subject: SND 12 01 003 #003 - D&C OBM Spill 06/19/2019

Attached is C-141 for oil based mud that occurred at Patterson Rig 816 at SND 12 01 003 #003 on June 19, 2019.

Josie DeLeon, HES Specialist -

Compliance Support - Environmental

Chevron - MCBU

(Carlsbad, Hobbs, Eunice, Vacuum, Buckeye Gas Plant)

1616 W. Bender Blvd.

Hobbs, NM 88240

575-263-0424

432-425-1528 - cell

jdx@chevron.com