

Hamlet, Robert, EMNRD

From: Hamlet, Robert, EMNRD
Sent: Tuesday, July 9, 2019 10:59 AM
To: DeAnn Grant
Cc: Venegas, Victoria, EMNRD; Bratcher, Mike, EMNRD; Ryan Mann; Jennifer Knowlton; Ike Tavarez; Robert McNeill; Sheldon Hitchcock; Dakota Neel; 'Rebecca Haskell'
Subject: RE: (C-141 Initial) Pine Springs 2 State SWD #001 (Illegal Dump) 06-12-2019 (2RP-5512) COG

RE: **COG * Pine Springs 2 State SWD #1 (Illegal Dump) * DOR: 06/12/2019**

All,

The OCD tracking number for this release event is **2RP-5512**.

Thank you,

Robert J Hamlet
State of New Mexico
Energy, Minerals, and Natural Resources
Oil Conservation Division
811 S. First St., Artesia NM 88210
(575) 840-5963
Robert.Hamlet@state.nm.us

From: Bustamante, Amalia, EMNRD <Amalia.Bustamante@state.nm.us>
Sent: Friday, July 5, 2019 11:51 AM
To: Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>
Subject: RE: (C-141 Initial) Pine Springs 2 State SWD #001 (Illegal Dump) 06-12-2019

2RP-5512

From: DeAnn Grant <agrant@concho.com>
Sent: Tuesday, June 25, 2019 8:52 AM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; Mann, Ryan <rmann@slo.state.nm.us>
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavarez <itavarez@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Initial) Pine Springs 2 State SWD #001 (Illegal Dump) 06-12-2019

Mr. Bratcher/Mr. Mann,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered

amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

DeAnn Grant

HSE Administrative Assistant

agrant@concho.com

COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701

Direct: 432-253-4513 | Main: 432.683.7443

