

Venegas, Victoria, EMNRD

From: Watson, Debbie <Deborah.Watson@wpxenergy.com>
Sent: Friday, June 21, 2019 2:58 PM
To: Griswold, Jim, EMNRD; Bratcher, Mike, EMNRD; Amos, James; Venegas, Victoria, EMNRD; Hamlet, Robert, EMNRD
Subject: [EXT] Ross Draw Unit #055 Release Notification

Good Afternoon,

Here is an update of the spill at the Ross Draw Unit #55:

Well: Ross Draw Unit #055
API: 30-015-41976
Surface: H-27-26S-30E
Well Location: 32.01615, -103.86379
Spill Location: flowline between wellhead and tank battery
Date of Release: June 21, 2019 @ 4:30 AM
Volume Released: Estimated 25-30 bbl unseparated production fluids
Volume Recovered: 10 bbl unseparated production fluids (as of 2:00 pm)

Flowline ruptured between wellhead and tank battery. Upon discovery, well was shut-in and truck called to recover fluids. Most of the fluids remained within the roadway with minor impact to adjacent pasture. I will email an impact map early next week.

Please contact me with any questions. Thank you.

Have a great weekend,

Debbie

Deborah Watson
Environmental Specialist
5315 Buena Vista Drive | Carlsbad, NM 88220
office 575.885.7561 | cell 505.386.9693
deborah.watson@wpxenergy.com



If you have received this message in error, please reply to advise the sender of the error and then immediately delete this message. Thank you.