

Venegas, Victoria, EMNRD

From: Baker, Adrian <Adrian_Baker@xtoenergy.com>
Sent: Tuesday, October 1, 2019 3:20 PM
To: Bratcher, Mike, EMNRD; Hamlet, Robert, EMNRD; Venegas, Victoria, EMNRD
Cc: Littrell, Kyle; Ruth, Amy; Foust, Bryan
Subject: [EXT] RE: Containment Inspection - Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR #007H) spill date 9-15-19

Good afternoon,

Below is a 48-hour email notification for liner inspection at the Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR #007H) spill date 9-15-19. We are unable to inspect the liner this week due to all of the recent rain in the area. The facility is located on a road that is currently underwater and impassible at this time. We are hoping to inspect the liner on Monday October 7, 2019.

Thank you

Adrian Baker
Safety, Health & Environmental Coordinator
[Permian Business Unit](#)

XTO Energy Inc.
6401 N. Holiday Hill Dr.
Midland, Tx 79707
Mobile:(432)-236-3808
adrian_baker@xtoenergy.com

From: Baker, Adrian
Sent: Monday, September 30, 2019 11:11 AM
To: 'Mike Bratcher' <mike.bratcher@state.nm.us>; 'Rob Hamlet' <robert.hamlet@state.nm.us>; 'Venegas, Victoria, EMNRD' <Victoria.Venegas@state.nm.us>
Cc: Littrell, Kyle <Kyle_Littrell@xtoenergy.com>; Ruth, Amy <Amy_Ruth@xtoenergy.com>; Foust, Bryan <Bryan_Foust@xtoenergy.com>
Subject: Containment Inspection - Ross Ranch 33-25-30 CTB - 30-015-40762 (API for Poker Lake CVX JV RR #007H) spill date 9-15-19

Good morning,

This is sent as 48-hour notification that we are scheduled to inspect this lined tank battery containment on October 2, 2019 at 1100 pm MST. We will be submitting the Initial/Final C-141 on October 2, 2019.

GPS: 32.09301, -103.89244

Thank you
Adrian Baker
Safety, Health & Environmental Coordinator
Permian Business Unit

XTO Energy Inc.
6401 N. Holiday Hill Dr.
Midland, Tx 79707
Mobile:(432)-236-3808
adrian_baker@xtoenergy.com