

Venegas, Victoria, EMNRD

From: Venegas, Victoria, EMNRD
Sent: Wednesday, June 12, 2019 11:56 AM
To: 'DeAnn Grant'; Bratcher, Mike, EMNRD; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD; dmckinne@blm.gov; Jennifer Knowlton; Ike Tavaréz; Robert McNeill; Sheldon Hitchcock; Dakota Neel; Rebecca Haskell
Subject: RE: (C-141 Initial) Cabo Wabo 25 Federal Com #003H 05-17-2019

RE: (C-141 Initial) Cabo Wabo 25 Federal Com #003H 05-17-2019

All,
The OCD tracking number for this release event is **2RP-5473**.
Thank you,

Victoria Venegas
EMNRD
OCD-District II
811 S First St. Artesia
NM 88210
Victoria.Venegas@state.nm.us

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to groundwater, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

From: DeAnn Grant <agrant@concho.com>
Sent: Tuesday, June 4, 2019 3:55 PM
To: Bratcher, Mike, EMNRD <mike.bratcher@state.nm.us>; jamos@blm.gov
Cc: Hamlet, Robert, EMNRD <Robert.Hamlet@state.nm.us>; Venegas, Victoria, EMNRD <Victoria.Venegas@state.nm.us>; dmckinne@blm.gov; Jennifer Knowlton <jknowlton@concho.com>; Ike Tavaréz <itavaréz@concho.com>; Robert McNeill <RMcNeill@concho.com>; Sheldon Hitchcock <SLHitchcock@concho.com>; Dakota Neel <DNeel2@concho.com>; Rebecca Haskell <RHaskell@concho.com>; DeAnn Grant <agrant@concho.com>
Subject: [EXT] (C-141 Initial) Cabo Wabo 25 Federal Com #003H 05-17-2019

Mr. Bratcher/Mr. Amos,

Please find the attached C-141 for your consideration. Also, attached is the calculation sheet to determine the estimated release volume. The liquid lost estimate is based on the spill dimensions, estimated depth of fluid (wet soil depth) and type of formation. The spreadsheet will calculate the volume lost in the ground and does not include the recovered amount in the calculation. The calculated volume in the ground and the volume recovered were added together and reported on the C-141. If you have any questions or concerns please do not hesitate to contact me.

Thank you,

DeAnn Grant
HSE Administrative Assistant
agrant@concho.com
COG Operating LLC

600 W Illinois Avenue | Midland, TX 79701
Direct: 432-253-4513 | Main: 432.683.7443

