Page 10 of 10

	1 ugc 10 oj
Incident ID	NAB1903733353
District RP	2RP-5222
Facility ID	
Application ID	pAB1903732371

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.		
A scaled site and sampling diagram as described in 19.15.29.11 NMAC		
New Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)		
Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)		
Description of remediation activities		
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of	tions. The responsible party acknowledges they must substantially nditions that existed prior to the release or their final land use in	
Printed Name: Wesley Mathews	Title: Environmental Representative	
Signature: Wesley Mathews	Date: _1/27/2020	
email:wesley.mathews@dvn.com	Telephone:575-578-6195	
OCD Only		
Received by: Victoria Venegas	Date: 01/27/2020	
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.	
Closure Approved by: CLOSURE DENIED	Date: <u>03/20/202</u> 0	
Printed Name: Victoria Venegas	Title: Engineering Tech. III	