

Devon Energy 333 West Sheridan Avenue Oklahoma City, OK 73102-5015 405 235 3611 Phone www.devonenergy.com

May 11, 2020

Mr. Bradford Billings 1220 S. St. Francis Dr. Santa Fe, NM 87505

Dear Mr. Billings:

The following attachments contain the original C-141 dated 5/14/2018 for the Boomslang 14-23 Federal #1 30-025-42920, incident number nOY1815243088. The release was reported as a gas release of 152 MCF. Also, attached is a closure for the above release. Given the nature of the release was gas, the closure report is absent a scaled site and sampling diagram, photographs of the remediation, laboratory analysis of sampling, and a description of remediation activities.

Please feel free to contact me if you have any questions or concerns.

Sincerely,

Amanda Trujillo Davis Environmental Representative

Devon Energy Corporation 6488 Seven Rivers Highway Artesia, New Mexico 88210 (575) 748-0176 Direct (505) 350-1336 Mobile Name of Company Devon Energy Production Company

Address 6488 Seven Rivers Hwy Artesia, NM 88210

Facility Name Boomslang 14-23 Fed 1H

Form C-141

Final Report

Revised April 3, 2017

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

☐ Initial Report

Release Notification and Corrective Action

OPERATOR

Facility Type Oil

Telephone No. 575-748-3371

Contact Merle Lewis, Production Foreman

Surface Owner Private Mineral Owner						Federal			API No. 30-025-42920	
LOCATION OF RELEASE										
Unit Letter B	Section 14	Township 24S	Range 33E	Feet from the 200'	North/ FNL	South Line	Feet from the 1980'	East/We FEL	est Line	County Lea
Latitude_32.2243153_ Longitude_103.5410047_ NAD83										
NATURE OF RELEASE										
Type of Release Natural Gas						Volume of Release 152 MCF			Volume R 0 MCF	Recovered
Source of Release Compressor gasket						Date and Hour of Occurrence May 11, 2018 @ 10:40 PM Date and May 11,			Date and	Hour of Discovery 2018 @ 10:40 PM
Was Immedia	ate Notice (No Not Ro	equired	If YES, To Whom? N/A					
By Whom? N/A						Date and Hour N/A				
Was a Watercourse Reached? ☐ Yes ☒ No						If YES, Volume Impacting the Watercourse. N/A				
If a Watercourse was Impacted, Describe Fully.* N/A Describe Cause of Problem and Remedial Action Taken.* Main compressors 1 inch big joe regulator on discharge line for supply gas going to blow case blew a gasket. Regulator and discharge line isolated and compressor was shut down.										
Describe Area Affected and Cleanup Action Taken.* Approximately 152 MCF released. 0 MCF recovered.										
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.										
							OIL CON	SERVA	ATION	DIVISION
Signature: Sheila Fisher Printed Name: Sheila Fisher										
						Approved by Environmental Specialist				
Title: Field	Title: Field Admin Support					Approval Dat	6/1/2018	<u> </u>	n]	Date:
E-mail Address: Sheila.Fisher@dvn.com						Conditions of Approval:				Attached
Date: 5/14/18 Phone: 575.748.1829 Attach Additional Sheets If Necessary										

nOY1815243088

Boomslang 14-23 Fed 1H 152 MCF_5.11.18



This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere Prepared by: Sheila Fisher Map is current as of: 14-May-2018

Miles 0.04 1: 1,779 0.02



Received by OCD: 5/11/2020 1:34:41 PM Form C-141 State of New Mexico Page 6 Oil Conservation Division

	Page 4 of 4
Incident ID	
District RP	
Facility ID	
Application ID	

Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.								
☐ A scaled site and sampling diagram as described in 19.15.29.11 NMAC								
Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)								
☐ Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)								
☐ Description of remediation activities								
and regulations all operators are required to report and/or file certain may endanger public health or the environment. The acceptance of should their operations have failed to adequately investigate and rerhuman health or the environment. In addition, OCD acceptance of compliance with any other federal, state, or local laws and/or regular restore, reclaim, and re-vegetate the impacted surface area to the coaccordance with 19.15.29.13 NMAC including notification to the O	ations. The responsible party acknowledges they must substantially anditions that existed prior to the release or their final land use in OCD when reclamation and re-vegetation are complete.							
Printed Name: Amanda Trujillo Davis	Title: Environmental Professional							
Printed Name: Amanda Trujillo Davis Signature:	Date: <u>5/11/2020</u>							
email: _amanda.davis@dvn.com	Telephone: 575-748-0176							
OCD Only								
Received by:	Date:							
	of liability should their operations have failed to adequately investigate and water, human health, or the environment nor does not relieve the responsible or regulations.							
Closure Approved by:	Date:							
Printed Name:	Title:							