

Venegas, Victoria, EMNRD

From: Barnhill, Amy D. <ABarnhill@chevron.com>
Sent: Wednesday, August 12, 2020 2:52 PM
To: EMNRD-OCD-District1spills
Subject: [EXT] Liner Inspections

To Whom it may concern,

Chevron had two spills recently in a lined containment. The fluids were picked via vac truck and the liners are still intact. We are planning to do inspections of the liners on Friday 8-14-2020. We have not filed the initial C-141s yet but plan to do that after the liner inspections. Below are the sites, please let me know if you need any other information from me..

McCloy Ranch – spill date: 8-1-2020 – GPS coordinates: 32.2394; -103.6478

Salado Draw 13 SWD – spill date: 8-10-2020 – GPS coordinates: N 32.02.19.22, W-103.38.26.24

Thank you,

Amy Barnhill

HES Specialist - Waste and Water

MCBU

6301 Deauville Blvd

Midland, TX 79706

Office: 432-687-7108

Cell: 432-940-8524

E-Mail: ABarnhill@chevron.com

#OurEnvironmentMatters

"The highest performance you can expect is the lowest standard you set"



CONFIDENTIALITY NOTICE: This message is confidential and may be privileged. If you believe that this email has been sent to you in error, please reply to the sender that you received the message; then please delete this email.