

From: Velez, Nelson, EMNRD
Sent: Monday, July 25, 2022 2:06 PM
To: Amber Groves
Cc: Bratcher, Mike, EMNRD
Subject: Frontier Field Services, LLC – Limousine Receiver, Incident #: NAB1902335282, Application ID: 109034

This email is applicable toward the approved closure for the aforementioned incident and for the intention of any future reportable releases where Frontier Field Services, LLC (Frontier) is the responsible party.

The following are notes of the final closure review;

1. No supporting data presented for:
 - a. lateral extents of the release if within 300 feet of a continuously flowing watercourse or any other significant watercourse - (topographic scale too small in Figure 1 to make determination)
 - b. lateral extents of the release if within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark) - (topographic scale too small in Figure 1 to make determination)
 - c. lateral extents of the release if within 300 feet of an occupied permanent residence, school, hospital, institution, or church
 - d. lateral extents of the release if within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes - (topographic scale too small in Figure 1 to make determination)
 - e. the lateral extents of the release if within 1000 feet of any other fresh water well or spring - (topographic scale too small in Figure 1 to make determination)
 - f. lateral extents of the release if within incorporated municipal boundaries or within a defined municipal fresh water well field
 - g. lateral extents of the release if within 300 feet of a wetland - (topographic scale too small in Figure 1 to make determination)
 - h. lateral extents of the release if overlying a subsurface mine
 - i. lateral extents of the release if within a 100-year floodplain
2. Photos deficient; no data presented for: GIS coordinates or location ID (e.g. - using point of reference) for photographs collected, no informational description(s) for imagery content
3. No field data presented for any field screening noted within report

Information presented in the final report was satisfactory for closure approval. This determination was based on the information within report summary write up, site map details, and sampling results.

OCD will evaluate future incidents based on site specific details but will hold Frontier accountable to fulfill its obligation in meeting the applicable requirements within Part 29 or Part 30 if pertinent. Therefore, any future reportable incident must adhere to the required application of 19.15.29.11 NMAC and 19.15.29.12 NMAC for OCD to render final closure approved. Failure in doing so may result in denial of the closure request.

Regards,

Nelson Velez • Environmental Specialist - Adv
Environmental Bureau | EMNRD - Oil Conservation Division
1000 Rio Brazos Road | Aztec, NM 87410
(505) 469-6146 | nelson.velez@state.nm.us

Hrs.: 7:00–11:00 am & 12:00–3:30 pm Mon.–Thur.
7:00–11:00 am & 12:00–4:00 pm Fri.