District | - (505):393-6161 P.O. Box 1980 Hobbs, NM 88241-1980 District II - (505) 748-1283 1301 W. Grand Ave. Artesia, NM 88210 **District III** - (505) 334-6178 1000 Rio Brazos Road

District IV - (505) 827-7131

Aztec, NM 87410

State of New Mexico

Energy Mineral and Natural Resources Department Oil Conservation Division 1220 South St. Francis Drive Santa Fe, New Mexico 87505

(505) 476-3440

Form C-141 Originated 2/13/97

Submit 2 copies to Appropriate District Office in accordance with Rule 116 on back side of form

30-015-30112				Release Notification and Corrective Action								
MC50406346429.				0	PERATOR				Initia	al Report	Final Report	
Name Co						ontact				ie .		
							leman					
Audiess						Telephone No.						
						05-457-2621 ext 103						
1 1 1							cility Type					
On location with Rocky Hills #1							water storag	e				
Dufare Ourse								li aa	11-			
Surface Owner Mineral Owner BLM BLM						Lease No. NM 0238436						
LOCATION OF RELEASE												
Unit Letter	Section	Township	Range	Feet from the	North/South	Line	Feet from the	East/West Line	Cou	•		
L	19	21 S	24 E	0	0		0	0	<u> </u>	Edd	ly	
NATURE OF RELEASE												
Type of Release							Volume of Release			Volume Recovered		
Produced water						4	379 Date of Occurrence Hour of Occurrence			30		
Source of Release						ן י	Date of Occurrence			Date of Discovery	Hour of Discovery	
Broken check valve on pump suction line Was Immediate Notice Given?						If VE	02/14/04 S, To Whom?	12:00 PN	4 1	02/16/04	9:00 AM	
was ininicula	14011CE (5)		es 🗀	No No	ot Required		e Bratcher					
By Whom?						IVIIX	Date of Notification			Hour of Notification		
Dwight Brodbeck						1	02/16/04			4:00 PM		
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.					
		L	Yes	No		1						
If a watercourse was Impacted, Describe Fully. (Attach Additional Sheets If Necessary)												
RECEIVED												
No Describe Cause	of Problem	and Remedial	Action Taker	/Attach Additions	Shoote if Naco	sean/)			_			
Describe Cause of Problem and Remedial Action Taken. (Attach Additional Sheets if Necessary										PEB 2	8 2004	
										OCD-A	RTESIA	
OCD-ARTESIA												
A 3 inch check valve on the water transfer pump suction froze and busted, allowing the tanks to drain. Describe Area Affected and Cleanup Action Taken. (Attach Additional Sheets if Necessary)												
See attachment.												
hereby certify the	nat the infon	mation given ab	ove is true a	nd complete to the	best of my know	dedge a	nd understand that	oursuant to NMOCI) rules	and regulation all or	perators are required	
											of a C-141 report by	
										nd remediate contar		
hread to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
	autui, outu,	0. 10001 10110 0.	raror regulat			T		CONCEDY	ATIC	N DIVICION		
Santa RV/Class							OIL CONSERVATION DIVISION TIM W. GUM					
Signature:		eu				-	(C)					
							ved by	DISTRIC		T ALDERV		
Printed Name: RV COLEMAN							t Supervisor: val Date:	1/2011	Evnin	ation Date:	`n.s.	
Date: Phone:							itions of Approval:	/ Z004.	CAPITO	Attached [
						Cond	nuona or Approval.			CHARLIEU		
۷.	-10-0	/	(5)	05) 457-2621		<u> </u>						

Instructions Workbook

Upon completion of this form, return to the Instructions Workbook

art i ski komanjali, i

f Faced to Landowner. (BLA)

Wil comple. to chlorites