

1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit Original
Plus 1 Copy
to Santa Fe

PIT INVENTORY FORM

Operator: CBS OPERATING CORP.

30-015-32912

Address: P. O. Box 2236

Midland TX 79702

Phone Number: 432/685-0878

Previous Operator(s): None

Is the pit permitted: Yes ☐ No ☒

Unit Letter: A Section: 33 Township: 16S Range: 31E

County: Eddy

Location Name: North Square Lake Unit Well No. 194

Number of wells to the pit: One

Are the wells to the pit operated by one operator ☒ or multiple operators ☐

Total daily volume (in barrels) to the pit: None

Pit Type: Reserve/drilling

(Emergency, Production, Workover, Reserve/Drilling (greater than 6 months old), Flare, Blowdown, Separator, Dehydrator, Line Drip, BS&W/Tank Bottoms, Compressor, Pigging, Washdown, or other)

What types of wastes are accepted in the pit (Exempt, Non-exempt, Both, None): Exempt

Pit age (years): 7 months

Is the pit lined ☒ or unlined ☐

Type of liner (None, Synthetic, Clay): Synthetic

Is leak detection present: Yes ☐ No ☒

Is the pit netted: Yes ☐ No ☒

Pit dimensions (LxWxD): 60'x100'x6'

CERTIFICATION

I hereby certify that the information submitted is true and correct to the best of my knowledge and belief.

Signature: M. A. Sirgo, III

Title: Engineer

Printed Name: M. A. Sirgo, III

Date: June 30, 2004

E-mail Address: mastres@aol.com

A pit is defined as any below grade or surface feature which receives any materials other than fresh water.

