

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO. 30-005-63600
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Selden BDN Com
8. Well Number 1
9. OGRID Number 025575
10. Pool name or Wildcat Undesignated Precambrian

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☐ Gas Well ☒ Other

RECEIVED

2. Name of Operator
Yates Petroleum Corporation

NOV 11 2004

3. Address of Operator
105 S. 4th Street, Artesia, NM 88210

~~OCD-ARTESIA~~

4. Well Location
Unit Letter H : 1650 feet from the North line and 660 feet from the East line
Section 35 Township 9S Range 24E NMPM Chaves County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)
3564'GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDON ☐
CASING/CEMENT JOB ☐

OTHER: Intermediate casing ☒

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11/2/04 - TD 11" hole at 6:30 PM. Set 8-5/8" 24# J-55 8rd ST&C casing at 1628'. Cemented with 100 sx RFC with 5#/sx D24 + .25#/sx C29 (yld 1.6, wt 14.2). and 300 sx 35:65 Poz "C" with 6% D20 + 5% D44 + 3% S1 + .2% D46 + 5#/sx D24 (yld 2.1, wt 12.6). Tailed in with 200 sx "C" with 2% S1 (yld 1.32, wt 14.8). Cement did not circulate. Calc. TOC 700' - sporadic returns thru cement job but no circulation re-established. WOC 18 hrs 30 mins. Tested casing to 1500 psi for 30 mins. Reduced hole to 7-7/8" and resumed drilling.

Note: Sundry dated November 2, 2004 incorrectly reported reducing hole to 7-7/8" and should have been reduced to 11".

RECEIVED

NOV 11 2004

~~OCD-ARTESIA~~

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Tina Huerta TITLE Regulatory Compliance Supervisor DATE November 8, 2004

Type or print name Tina Huerta E-mail address: tinah@ypcnm.com Telephone No. 505-748-1471

For State Use Only

APPROVED BY: _____ TITLE _____ DATE NOV 19 2004

Conditions of Approval (if any): _____

FOR RECORDS ONLY