

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-005-63648

Release Notification and Corrective Action

OPERATOR

X Initial Report ☐ Final Report

Name of Company Yates Petroleum Corporation	Contact Dan Dolan
Address 105 South 4 th Street, Artesia, New Mexico, 88210	Telephone No. 505-748-1471
Facility Name Cooker BCB Fed. Com. #2	Facility Type Drilling Pit

Surface Owner Federal	Mineral Owner	Lease No.
-----------------------	---------------	-----------

LOCATION OF RELEASE

Unit Letter A	Section 21	Township 6s	Range 26e	Feet from the	North/South Line	Feet from the	East/West Line	County Chaves
------------------	---------------	----------------	--------------	---------------	------------------	---------------	----------------	------------------

Latitude 33.78484 Longitude 104.29558

NATURE OF RELEASE

Type of Release Fresh Water & Possible drilling pit contents.	Volume of Release NA	Volume Recovered -0-
Source of Release Drilling pit	Date and Hour of Occurrence NA	Date and Hour of Discovery 10/17/2004
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No X Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

RECEIVED

NOV 02 2004

ARTESIA

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Due to heavy rains in the area of the location, the drilling pit received and influx of rain water. The west side of the drilling reserve pit ruptured allowing rain water and possible drilling pit contents to run into the area located due south & west of the drilling pit. The drilling pit west wall was reconstructed. The area of possible impact will be sampled and a corrective action workplan or final C-141 form will be submitted to the O.C.D. depending on sampling results.

Describe Area Affected and Cleanup Action Taken.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: *Mike Stubblefield*

Printed Name: Mike Stubblefield

Title: Reclamation Agent

E-mail Address:

Date: 11/1/2004

Phone: 748-4500

Approved by District Supervisor:

Approval Date: 12/6/04

Conditions of Approval:

Expiration Date: 3/6/05

Attached ☐