

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 12/9/2014
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Dorado 34 Fed Com #1H	Facility Type: Oil producing Well

Surface Owner: BLM	Mineral Owner: BLM	API No. 30-015-38984
--------------------	--------------------	----------------------

LOCATION OF RELEASE

Unit Letter I	Section 34	Township 18S	Range 30E	Feet from the 1850'	North/South Line South	Feet from the 620'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.7017932 Longitude -103.9532871

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: estimated 110 bbls total fluid	Volume Recovered: Oil (100 bbls)
Source of Release: Oil tank's load line	Date and Hour of Occurrence 11-1-14	Date and Hour of Discovery 11-1-14 2:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Eddy County Sherriff Department	
By Whom? Jaime Hobbs	Date and Hour 11-1-14 5:30 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Cause of the leak- Load line seals on every oil tank were cut and valves were opened including main load line for oil trucks, releasing an estimated 110 bbls of oil on pad surface directly outside secondary containment. Upon discovery by water hauler, main load line was shut in order to stop the release.

Describe Area Affected and Cleanup Action Taken.*

Affected area- Pad surface in between pumping unit and secondary containment. JWS vacuum trucks were used to recover 100 bbls of oil on pad surface. All contaminated soil was removed and disposed at an approved NMOCD disposal site. Soil samples for BTEX and TPH were taken at 1.5' bgs and came back clean according to the remediation action levels.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Zack Thomas	Approved by Environmental Specialist:		
Title: Environmental Rep.	Approval Date: 12/15/2014	Expiration Date: NA	
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: 11-3-14	Phone: 575-602-2188		

2RP-2574