Rec'd 4/7/15 NMOCD Dist 2

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe. NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action OPERATOR Initial Report Final Report Name of Company Devon Energy Production **Contact** Rudy Zuniga, Production Foreman **Telephone No.** 575-390-5435 Address 6488 Seven Rivers Hwy Artesia, NM 88220 Facility Name Onyx PWU 29 2H Facility Type Oil **Surface Owner State Mineral Owner State API No.** 30-015-39373 LOCATION OF RELEASE Unit Letter Feet from the North/South Line Feet from the East/West Line Section Township Range County E 29 19S 29E 2310 N 330 W Eddy **Latitude:** 32.6327760 **Longitude:** 104.1045141 NATURE OF RELEASE Type of Release Spill Oil Volume of Release 1bbl Volume Recovered Obbl Source of Release Flare **Date and Hour of Occurrence Date and Hour of Discovery** March 18, 2015 8:10 AM March 18, 2015 8:10 AM Was Immediate Notice Given? If YES, To Whom?

Mike Bratcher, OCD Jeff Robertson, BLM

By Whom? Ray Carter, Asst. Production Foreman OCD March 18, 2015 9:30 AM BLM March 18, 2015 9:45 AM Was a Watercourse Reached? ☐ Yes ☑ No Date and Hour OCD March 18, 2015 9:30 AM BLM March 18, 2015 9:45 AM If YES, Volume Impacting the Watercourse N/A

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

The low pressure separator had some trash and rubber stuck in the dump which caused the separator to flood and send fluid into both the gas line and the supply gas for the high pressure separator, once the dump for the high pressure separator was overloaded it sent 1bbl of oil in a mist out the flare line onto location and pasture. The separators were immediately drained and the gas lines were cleared.

Describe Area Affected and Cleanup Action Taken.*

The area affected is 30x30 on the pad and into the pasture on the Southwest corner approximately 15 feet. The location will be back dragged and the pasture will be pressure washed with Dawn soap.

The location was back dragged and the pasture was pressure washed with Dawn Soap on April 1, 2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION		
Printed Name: Sheila Fisher	Approved by Environmental Specialist:		
Title: Field Admin Support	Approval Date: 4/8/15	Expiration Date: N/A	
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval: N/A FINAL		Attached
Date: 4/6/15 Phone: 575.748.1829			

^{*} Attach Additional Sheets If Necessary