

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 4/8/2015  
NMOCD Artesia

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Wild Cap State Com #5H	Facility Type: Wellhead

Surface Owner: State	Mineral Owner: State	API No. 30-015-37144
----------------------	----------------------	----------------------

### LOCATION OF RELEASE

Unit Letter C	Section 36	Township 19S	Range 31E	Feet from the 330	North/South Line North	Feet from the 2260	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.6233208635271 Longitude-103.823902727635

### NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 30 bbls oil	Volume Recovered: 25 bbls oil
Source of Release: wellhead	Date and Hour of Occurrence: 1-29-2015 7:00 am	Date and Hour of Discovery: 1-29-2015 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Tomas Oberding - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: 1/30/2015 5:52 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

This release was caused when a pulling unit crew left a hold down pin loose in the wellhead and it caused a blowout. Crews reinstalled the pin and was able to stop the blow out.

Describe Area Affected and Cleanup Action Taken.\*

The affected was the pad and the pasture to the southwest and northeast corner of the pad. The impact was a light mist. Crews scraped the pad and microblazed the pasture. Samples were taken from these areas and were within RRALs per OCD Guidelines Leaks, Spills and Releases (1993) for a site ranking of zero (0).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 4/13/2015	Expiration Date: N/A
E-mail Address: <a href="mailto:atrujillo@concho.com">atrujillo@concho.com</a>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: April 8, 2015	Phone: 575-748-6940	FINAL

\* Attach Additional Sheets If Necessary

2RP-2811