

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 4/10/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Shiner Bock IFederal Com #1	Facility Type: Well

Surface Owner: Federal	Mineral Owner: Federal	API No.30-015-42015
------------------------	------------------------	---------------------

LOCATION OF RELEASE

Unit Letter P	Section 2	Township 17S	Range 31E	Feet from the 990	North/South Line South	Feet from the 150	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.8574867089099 Longitude -103.831868316424

NATURE OF RELEASE


Type of Release: Produced Water	Volume of Release: 20 bbls	Volume Recovered: 0 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 12/18/2014 8:16 am	Date and Hour of Discovery: 12/18/2014 8:16 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release was caused by a hole in 4" gas line; gas released was ignited by static electricity from nearby power lines. This created small fire and melted 4" water line next to it. The lines were isolated to stop gas and water.

Describe Area Affected and Cleanup Action Taken.*
An area approximately 30' x 50' was impacted in the pasture near the flowline. Concho had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD and the BLM for approval prior to any significant remediation work. All work has been completed in accordance with the approved work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Garrett B. Merket	Approved by Environmental Specialist:		
Title: Environmental Coordinator	Approval Date: 4/14/2015	Expiration Date: N/A	
E-mail Address: gmerket@concho.com	Conditions of Approval: FINAL		Attached <input type="checkbox"/>
Date: April 10, 2015	Phone: 432-234-0490		

* Attach Additional Sheets If Necessary