

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 4/28/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Cooper 29 Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-36932
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter L	Section 29	Township 25S	Range 29E	Feet from the 2230	North/South Line South	Feet from the 560	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.0997469065957 Longitude -104.013226365386

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 20 bbls	Volume Recovered: 18 bbls
Source of Release: Flowline	Date and Hour of Occurrence: 10-17-2014 1:51 am	Date and Hour of Discovery: 10-17-2014 1:51 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher – OCD / Jeffery Robertson – BLM	
By Whom? Amanda Trujillo	Date and Hour: 10/27/2014 10:34 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a flowline leak. A issue in the SWD system caused the line to pressure up. Vacuum trucks were dispatched to pick up standing fluid. Repairs were made to the line.

Describe Area Affected and Cleanup Action Taken.*

The impacted area was approximately 300' x 1.5' in size in the pasture. Concho had the spill site sampled to delineate any possible contamination from the release and presented a remediation work plan to the NMOCD and BLM for approval prior to any significant remediation work. All work has been completed in accordance to the approved work plan and revisions.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Lupe Carrasco		Approved by Environmental Specialist:	
Title: Environmental Coordinator		Approval Date: 5/1/2015	Expiration Date: N/A
E-mail Address: gcarrasco@concho.com		Conditions of Approval:	
Date: April 28, 2015 Phone: 575-748-6940		FINAL	
		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

2RP-2584