

District I
1625 N. French Dr , Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Latigo Petroleum, Inc	Contact Pat Ellis
Address P.O. Box 10340 Midland, TX 79702	Telephone No. (432) 685-8148
Facility Name Marine 19 Federal #1	Facility Type Tank Battery

Surface Owner	Mineral Owner	Lease No. NM - 109756
---------------	---------------	-----------------------

LOCATION OF RELEASE

Unit Letter E	Section 19	Township 25S	Range 27E	Feet from the 1480	North/South Line North	Feet from the 1130	East/West Line West	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32° 07' 06" Longitude 104° 14' 01"

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 200 BBLS	Volume Recovered 780 BBLS (Produced Water / Rain Water)
Source of Release Fiberglass Water Tank	Date and Hour of Occurrence	Date and Hour of Discovery 3-21-07 10:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Left voice message Mike Bratcher - OCD Tammy - BLM	
By Whom? Patrick Ellis	Date and Hour 3-22-07 5:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Lightning storm struck fiberglass tank. The tank exploded releasing 200 BBLS of produced water which mixed with heavy rainfall.

Describe Area Affected and Cleanup Action Taken.*
Release occurred in a lined facility. A portion of the berm washed out allowing water mixture to reach the well pad. All free fluid was picked up. Highlander Environmental Corp. evaluated spill area for closure.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Patrick L. Ellis</i>		<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Patrick L. Ellis		Approved by District Supervisor: <i>Howe</i>	
Title: EH&S Supervisor		Approval Date: 8/6/2015	Expiration Date: N/A
E-mail Address: ellisp@pogoproducing.com		Conditions of Approval: FINAL	
Date: Phone: (432) 685-8148		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary