

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/18/2015

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company <i>COG Operating LLC</i>	Contact Robert McNeill
Address 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name Scared Hawk State Com #1	Facility Type Well

Surface Owner State	Mineral Owner	API No. 30-015-35102
---------------------	---------------	----------------------

LOCATION OF RELEASE

Unit Letter A	Section 4	Township 25S	Range 28E	Feet from the 330	North/South Line North	Feet from the 25	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	---------------------	------------------------	----------------

Latitude 32.165635431036 **Longitude** -104.083854368812

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 30 bbls PW	Volume Recovered 5 bbls PW
Source of Release Flowline	Date and Hour of Occurrence 3/8/2015 11:00 am	Date and Hour of Discovery 3/8/2015 11:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour 3/9/2015 5:49 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

This release was caused when the weld in a poly flowline failed to hold. Vacuum trucks were dispatched to recover any standing fluids.

Describe Area Affected and Cleanup Action Taken.*

The impacted area occurred within the pasture and road, approximately 150' x 90'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 8/25/2015	Expiration Date: NA
E-mail Address: atruiillowiconcho.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: August 8, 2015	Phone: 575-748-6940	

* Attach Additional Sheets If Necessary

2RP-2918