

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received 9/28/2015  
NMOCD Artesia

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company BOPCO, L.P.	Contact Tony Savoie
Address 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 432-556-8730
Facility Name Poker Lake Unit 213 SWD (2RP-1202)	Facility Type E&P

Surface Owner Federal	Mineral Owner Federal	Lease No. 30-015-33859
-----------------------	-----------------------	------------------------

**LOCATION OF RELEASE**

Unit Letter P	Section 18	Township 24S	Range 30E	Feet from the	North/South Line	Feet from the	East/West Line	County Eddy
------------------	---------------	-----------------	--------------	---------------	------------------	---------------	----------------	----------------

Latitude N 32.212505 Longitude W 103.914199

**NATURE OF RELEASE**


Type of Release: Produced water and crude oil	Volume of Release: 5 Bbbls of Produced water and 5 Bbbls crude oil	Volume Recovered: None
Source of Release: Tank Overflow	Date and Hour of Occurrence 5/28/12 Time unknown	Date and Hour of Discovery 5/28/12 10:00 p.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM	
By Whom? Tony Savoie	Date and Hour 5/29/12 8:55 a.m.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* The SWD tanks overflowed due to a pump malfunction and high level alarm failure. The water coming into the facility was diverted and the power was restored to the facility the next day

Describe Area Affected and Cleanup Action Taken.\* The SWD tanks are inside a poly lined metal containment which contained most of the released fluid, the wind was blowing extremely hard to the north west carrying the fluid outside of the containment and misting an area of approximately 23,400 sq. ft of pasture land with a fine mist of oil and water. The soil had less than 1/4' of saturation. ***This area was reviewed by the BLM 6-27-12 "no further action required."*** The area around the pumps and concrete pad area were affected by the release with a saturation of approximately 1 ft. in depth. The remediation will comply with the NMOCD and BLM requirements for spills. ***The spill area around the concrete pad area and road was sampled 2/16/15; the lab analysis was reviewed by the OCD on 3/4/15. Please find the attached soil closure request dated September 2015.***

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie		Approved by District Supervisor:	
Title: Waste Mgmt. & Remediation Specialist		Approval Date: 9/28/2015	Expiration Date: N/A
E-mail Address: TASavoie@BassPet.com		Conditions of Approval:	
Date: 9/28/15 Phone: 432-556-8730		Attached <input type="checkbox"/>	
		FINAL	

\* Attach Additional Sheets If Necessary

**2RP-1202**