

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 10/7/2015
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P.	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU-21-Legg Federal SWD Battery; 2RP#2695	Facility Type: SWD
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-04734	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	27	22S	30E	660	North	2004	East	Eddy

Latitude: N 32.368838° Longitude: W 104.090212°

NATURE OF RELEASE

Type of Release: crude oil and produced water	Volume of Release: 220 bbls crude oil, 279 bbls PW	Volume Recovered: 200 bbls crude oil, 279 bbls PW
Source of Release: 500 bbl skim tank	Date and Hour of Occurrence: 12/21/14 between 2 and 4 am	Date and Hour of Discovery: 12/21/14 @ 4 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD emergency #104	
By Whom? Tony Savoie	Date and Hour: 12/21/14 @ 3:10 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: Not Applicable	

If a Watercourse was Impacted, Describe Fully.* Not Applicable

Describe Cause of Problem and Remedial Action Taken.*
A motor valve failed sending all of the fluid to the skim tank causing it to over-flow. The vessel was by-passed until the motor valve could be replaced.

Describe Area Affected and Cleanup Action Taken.*
The skim tank was located in 0-perm containment capable of holding 382 bbls, the skim tank containment overflowed spilling approximately 27 bbls of crude oil on the ground and approximately 70 bbls into the adjoining containment around the gun barrel tanks. Seven bbls of oil was recovered off the ground and 193 bbls from the containments. Also spilled was 279 bbls of produced water which was all contained in the 0-perm. The spill impacted approximately 8,950 sq. ft. of caliche tank battery area. All of the free standing fluid was recovered and approximately 14 cubic yards of saturated soil was scraped up and placed on plastic during initial response. Samples were collected, and based on laboratory analytical data and NMOCD approval: the contaminated soil has been excavated with 54.64 tons hauled to a state approved disposal facility and the excavation backfilled with clean soil. The spill area has been cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<u>OIL CONSERVATION DIVISION</u>	
		Approved by Environmental Specialist:	
Printed Name: Bradley Blevins		Approval Date: 10/8/2015	Expiration Date: N/A
Title: Assistant Remediation Foreman		Conditions of Approval: FINAL	Attached <input type="checkbox"/>
E-mail Address: bblevins@basspet.com			
Date:	Phone: 432-214-3704		

* Attach Additional Sheets If Necessary