

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 1/8/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|-----------------|--|---------------|----------------------|
| Name of Company | COG Operating LLC | Contact | Robert McNeill |
| Address | 600 West Illinois Avenue, Midland TX 79701 | Telephone No. | 432-230-0077 |
| Facility Name | MOSSY FEDERAL #001H | Facility Type | Battery |
| Surface Owner | Federal | Mineral Owner | API No. 30-015-42735 |

LOCATION OF RELEASE

| Unit Letter | Section | Township | Range | Feet from the | North Line | Feet from the | East Line | County |
|-------------|---------|----------|-------|---------------|------------|---------------|-----------|--------|
| A | 12 | 20S | 29E | 990 | | 550 | | EDDY |

Latitude 32.592443 Longitude -104.02171

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|-------------------------------|----------------------------|----------------|
| Type of Release | Produced Water | Volume of Release | 120bbl PW | Volume Recovered | 40bbl PW |
| Source of Release | Loadout valve | Date and Hour of Occurrence | 11/4/15 5:00pm | Date and Hour of Discovery | 11/4/15 5:00pm |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required | If YES, To Whom? | Mike Bratcher – NMOCD (email) | | |
| By Whom? | Amanda Trujillo | Date and Hour | 11/5/2015 | 4:30 PM | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

The release was caused when a water hauler (M&R trucking) left the load out valve open, causing the water to leak out onto location. The release stayed within the confines of the locations pad.

Describe Area Affected and Cleanup Action Taken.*

150ft long by 75ft wide between the batteries loadout area and the pump jack. This release was addressed per the approved workplan and under the guidance of NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|---------------------------------------|----------------------|-----------------------------------|
| Signature:  | <u>OIL CONSERVATION DIVISION</u> | | |
| Printed Name: Amanda Trujillo Davis | Approved by Environmental Specialist: | | |
| Title: Environmental Coordinator | Approval Date: 1/12/2016 | Expiration Date: N/A | |
| E-mail Address: atrujillo@concho.com | Conditions of Approval: | | Attached <input type="checkbox"/> |
| Date: December 29, 2015 Phone: 575-689-3100 | FINAL | | |

* Attach Additional Sheets If Necessary

2RP-3403