

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nAB1522256800

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Mewbourne Oil Company	Contact: Zack Thomas
Address: PO Box 5270 Hobbs NM 88241	Telephone No. 575-393-5905
Facility Name: Santo Nino 29 Fed SWD #1	Facility Type: Producing Oil Well
Surface Owner: BLM	Mineral Owner: BLM
API No. 30-015-28689	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	29	18S	30E	1932'	North	1923'	East	Eddy

Latitude 32.720294 Longitude -103.992032

NATURE OF RELEASE

Type of Release: Produced water	Volume of Release: 1170 bbls	Volume Recovered: 1170 bbls
Source of Release: Water Tank	Date and Hour of Occurrence 6-13-15 6:30 pm	Date and Hour of Discovery 6-13-15 7:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM)	
By Whom? Robin Terrell	Date and Hour 6-14-15 11:30 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Cause of leak: The tank battery was struck by lightning. Upon being struck, the battery caught fire and burned a hole in the corner of the containment. Fire department was immediately contacted and vacuum trucks arrived to clean the spill as soon as the location was deemed safe.

Describe Area Affected and Cleanup Action Taken.*

Affected area: The produced water leaked out of the SW corner of the containment behind location. Vacuum trucks recovered all of the standing water and any visually contaminated soil was taken to an approved NMOCD disposal site. For complete remediation details reference work plan dated November 19, 2015 and closure report dated February 5, 2016. Final remediation was be conducted in accordance with the NMOCD's Guidelines for Remediation of Spills, Leaks and Releases.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Zack Thomas	Approved by Environmental Specialist: <i>MBratcher</i>	
Title: Environmental Rep.	Approval Date: 2/9/2016	Expiration Date: N/A
E-mail Address: zthomas@mewbourne.com	Conditions of Approval: Completion of project per approved plan	Attached <input type="checkbox"/>
Date: 2-5-16	Phone: 575-602-2188	

* Attach Additional Sheets If Necessary

Final Report

2RP-3194