

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 2/25/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Cypress 33 Federal #2H Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-37308	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	33	23S	29E					Eddy County, NM

Latitude N 32.26644°

Longitude W 103.98343°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	12 bbls oil, 13 bbls produced water	Volume Recovered	0 bbls
Source of Release	Valve was left open causing the tank to spill over	Date and Hour of Occurrence	04/22/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD, James Amos-BLM		
By Whom?	Kathy Purvis, BBC International	Date and Hour	04/28/2015 @ 9:41am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A valve was left open causing the tank to spill 12 bbls of oil and 13 bbls of produced water onto the ground. No fluids were recovered and the valve was placed in the correct position.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 75' x 100' with the spill staying on location. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 08/19/2015 and approved by Shelly Tucker of the BLM via email on 08/19/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:				<u>OIL CONSERVATION DIVISION</u>	
Printed Name:	Casey Summers	Approved by Environmental Specialist:			
Title:	NM Environmental Advisor	Approval Date:	2/29/2015	Expiration Date:	N/A
E-mail Address:	Casey_Summers@oxy.com	Conditions of Approval:	N/A	Attached	<input type="checkbox"/>
Date:	2-23-16	Phone:	(575) 513-8289	FINAL	

* Attach Additional Sheets If Necessary

2RP-2979