

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural ResourcesOil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Peaches 19 Federal #1 H SWD	Facility Type	SWD CTB
Surface Owner	Federal	Mineral Owner	
		API No. 30-015-40250	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	19	25S	27E	330'	North	2310'	East	Eddy County, NM

Latitude N 32.12176° Longitude W 104.22836°**NATURE OF RELEASE**

Type of Release	Produced water	Volume of Release	20 bbls	Volume Recovered	Unknown
Source of Release	Vandals/Human Error open load line	Date and Hour of Occurrence	04/20/2015	Date and Hour of Discovery	04/20/2015
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

The valve on load line was opened by vandals causing a release of 20 barrels of produced water on location at the load out.

Describe Area Affected and Cleanup Action Taken.*

The impacted area surrounding the produced water load out measures approximately 60' x 40'. All fluids stayed on location. Talon/LPE has already performed site assessment and soil sampling activities. Remediation was completed in accordance with the remediation plan approved by Heather Patterson of NMOCD via email on 06/01/2015.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>		
Printed Name: Casey Summers	Approved by Environmental Specialist:		
Title: NM Environmental Advisor	Approval Date: 3/1/2016	Expiration Date: N/A	
E-mail Address: <u>Casey_Summers@oxy.com</u>	Conditions of Approval:		Attached <input type="checkbox"/>
Date: <u>2-23-16</u> Phone: (575) 513-8289	FINAL		

* Attach Additional Sheets If Necessary

2RP-3020