

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company Yates Petroleum Corporation	Contact Amber Griffin
Address 104 S. 4 th Street	Telephone No. 575-748-1471
Facility Name - Livingston Ridge SWD Water Line (Wolf AJA Federal Com # 17H)	Facility Type Water Transfer Line

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-39829
--------------------------	--------------------------	-------------------------

LOCATION OF RELEASE

Unit Letter <u>D</u> <u>A</u>	Section 25	Township 21S	Range 31E	Feet from the 1920	North/South Line North	Feet from the 300	East/West Line East	County Eddy
-------------------------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.455771 Longitude 103.725007

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 50 B/PW	Volume Recovered 0 B/PW
Source of Release Poly line	Date and Hour of Occurrence 6/18/2015; AM	Date and Hour of Discovery 6/18/2015; PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Patterson, Randy Dade, & Jim Amos	
By Whom? Robert Asher/Yates Petroleum Corporation	Date and Hour 6/19/2015; AM (Email)	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		


Describe Cause of Problem and Remedial Action Taken.*

A water poly line split, causing the release. Vacuum truck(s) and roustabout crews were called. The wells were shut in and vacuum trucks were called to recover the spill, but no released produced water was recovered. A roustabout crew was called to repair the poly line.

Describe Area Affected and Cleanup Action Taken.*

An approximate total area of 0.6272 acres, with a pooling area of 0.0490 acres and an overspray area of 0.5782 acres. The overspray area will be treated with a 3% microblaze solution, and the pooling area will have vertical and horizontal delineation samples taken and analysis ran for TPH & BTEX (chlorides for documentation). Excavated soils will be hauled to a NMOCD approved facility. If initial analytical results for TPH & BTEX are under RRAL's (site ranking is 0) a Final Report, C-141 will be submitted to the OCD requesting closure. If the analytical results are above the RRAL's a work plan will be submitted to the OCD. **Depth to Ground Water: >100' (approximately 125', Section 25, T21S-R31E, per Trend Map), Wellhead Protection Area: No, Distance to Surface Water Body: >1000', SITE RANKING IS 0. Yates Petroleum requests closure based off all work being completed as per NMOCD approved work plan. 4' of contaminated soils were excavated from the release area, a 20 mil liner was installed in the bottom of the excavation, and the excavation was backfilled. Contaminated soils were taken to R360 Environmental Solutions on Highway 62/180. Overspray area analytical results are also attached for NMOCD records.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<u>OIL CONSERVATION DIVISION</u>	
Printed Name: Amber Griffin	Approved by Environmental Specialist:	
Title: NM Environmental Regulatory Agent	Approval Date: 4/7/2016	Expiration Date: N/A
E-mail Address: agriffin@yatespetroleum.com	Conditions of Approval: Unit Letter of spill is A (not D) depth to groundwater is less than 100' according to EDDY Co Trend Map. Contamination at 13'. Site Ranking is 10	
Date: April 6, 2016	Phone: 575-748-4111	Attached <input type="checkbox"/>

* Attach Additional Sheets If Necessary

2RP-3074