

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-685-4304
Facility Name: BUENA VISTA 2 STATE #001H	Facility Type: Battery

Surface Owner: State	Mineral Owner: State	API No. 30-015-40789
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter P	Section 02	Township 20S	Range 30E	Feet from the 1130'	North/South Line South	Feet from the 330'	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	------------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.5981522 Longitude -103.9353943

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 8 bbls PW	Volume Recovered: 5 bbls PW
Source of Release: Fittings/Connections	Date and Hour of Occurrence: 4/14/2016 10:00 am	Date and Hour of Discovery: 4/14/2016 10:00 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

This release was caused by a pipe fitting on battery lines. A vacuum truck was dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.*

This release occurred within the lined containment of the facility. Concho will have the spill site inspected to determine any possible contamination from the release. The containment has been cleaned and the impacted gravel has been removed. Fresh gravel has been placed inside the containment.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: 5/23/2016	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 05-20-2016 Phone: 432-685-4304	FINAL	

* Attach Additional Sheets If Necessary

2RP-3664