

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 6/2/2016
NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1615523982

OPERATOR

X Initial Report ☐ Final Report

Name of Company	XTO Energy, Inc. 5380	Contact	John Robinson
Address	500 W. Illinois, Suite 100, Midland, TX 79701	Telephone No.	575-441-5199
Facility Name	Corral Canyon Fed #4 H	Facility Type	Well

Surface Owner	BLM	Mineral Owner	BLM / NMSLO	API No.	30-015-42923
---------------	-----	---------------	-------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	5	T25S	R29E	200	South	760	East	Eddy

Latitude 32.152346°N Longitude 104.000009°W

NATURE OF RELEASE

Type of Release	Wellhead Fire Oil, Produced Water and Natural Gas	Volume of Release	1552 mcf. Due to fire we were not able to gauge fluids.	Volume Recovered	0
Source of Release	Wellhead	Date and Hour of Occurrence	5-21-16 4:00 am	Date and Hour of Discovery	5-21-16 4:00 am
Was Immediate Notice Given?	X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos BLM, Heather Patterson OCD			
By Whom?	John Robinson	Date and Hour	5-21-16 11:00 am		
Was a Watercourse Reached?	<input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Connection on wellhead failed and caused a leak. Something sparked and caught natural gas on fire. Once fire was out we sprayed overspray area with micro blaze and will clean up rest of contamination asap.

Describe Area Affected and Cleanup Action Taken.*

Fire was contained to wellhead area. Will take samples from contaminated area and clean up contaminated soil and replace with clean soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John Robinson	Approved by Environmental Specialist:	
Title: Maintenance Foreman	Approval Date: 6/3/2016	Expiration Date: N/A
E-mail Address: john_robinson@xtoenergy.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 6-2-16	Phone: 575-441-5199	

* Attach Additional Sheets If Necessary

Remediation per OCD Rules and Guidelines
Submit Remediation Proposal No Later
Than 7/3/2016

2RP-3713