

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 7/28/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	McKittrick Hills Central Tank Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-21010

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	14	22S	24E					Eddy County, NM

Latitude N 32.39755° Longitude W 104.46109°

NATURE OF RELEASE

Type of Release	Oil and Produced water	Volume of Release	20 bbls oil, 160 bbls produced water	Volume Recovered	160 bbls
Source of Release	Lack of alarms to warn of a tank overfill	Date and Hour of Occurrence	12/09/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher-NMOCD; Shelly Tucker-BLM		
By Whom?	Cliff Brunson @ BBC International	Date and Hour	12/10/2015 @ 5:00 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lack of alarms caused a tank to overfill spilling 20 bbls of oil and 160 bbls of produced water onto the ground. A vacuum truck recovered 160 bbls of fluids and the alarm issue was corrected.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 75' x 50' on location. Remediation was completed in accordance with a remediation plan approved by Mike Bratcher of NMOCD via email on 04/28/2016 and by Shelly Tucker of the BLM via email on 05/03/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: Casey Summers	Approved by Environmental Specialist:		
Title: NM Environmental Advisor	Approval Date: 8/5/2016	Expiration Date: N/A	
E-mail Address: Casey_Summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 7-26-16	Phone: (575) 513-8289	FINAL	

* Attach Additional Sheets If Necessary

2RP-3471