

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/5/2016

NMOCD Artesia

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company:	COG Operating LLC	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	CLUSTER STATE COM #001H	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:		API No.	30-015-37547
----------------	-------	----------------	--	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	16	26S	27E	380	North	330	West	Eddy

Latitude 32.0486679

Longitude 104.2026672

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 10bbls Produced Water	Volume Recovered: 9bbls of Produced Water
Source of Release: High Pressure Hose	Date and Hour of Occurrence: 06-02-2016 09:00am	Date and Hour of Discovery: 06-02-2016 09:00am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A high-pressure hose between the produced water tank and the transfer pump split due to age. The hose has been replaced with a new high-pressure hose.

Describe Area Affected and Cleanup Action Taken.*

The release was contained within a lined facility. A vacuum truck was dispatched to remove all freestanding fluids. The containment has been cleaned and the facility has been put back into operation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<u>OIL CONSERVATION DIVISION</u>				
Printed Name:	Robert Grubbs Jr.	Approved by Environmental Specialist:			
Title:	Senior Environmental Coordinator	Approval Date:	8/15/2016	Expiration Date:	N/A
E-mail Address:	rgrubbs@concho.com	Conditions of Approval:		Attached <input type="checkbox"/>	
Date:	August 5, 2016	Phone:		432-683-7443	

* Attach Additional Sheets If Necessary

2RP-3731