

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Received 10/4/2016

NMOCD Dist 2

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

nAB1608941057

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company	Oxy Permian Ltd.	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Peaches 19 Federal CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No. 30-015-40250	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	19	25S	27E					Eddy

Latitude N 32.12147° Longitude W 104.22839°

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	7 bbls oil, 2 bbls produced water	Volume Recovered	7 bbls
Source of Release	Heater gasket blew out	Date and Hour of Occurrence	03/03/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	03/04/2016 @ 3:29 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*


Describe Cause of Problem and Remedial Action Taken.\*

A heater gasket blew out causing a spill of 7 bbls of oil and 2 bbls of produced water. A vacuum truck recovered 7 bbls of fluids and the gasket was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 150' x 60' with most of the leak staying inside the lined containment. Remediation was completed in accordance with the remediation plan approved by Mike Bratcher of NMOCD via email on 04/28/2016 and approved by Shelly Tucker of the BLM via email on 06/13/2016.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Casey Summers		Approved by Environmental Specialist: <i>MBratcher</i>	
Title: NM Environmental Advisor		Approval Date: 10/5/16	Expiration Date: N/A
E-mail Address: Casey_Summers@oxy.com		Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 10-3-16	Phone: (575) 513-8289	FINAL	

\* Attach Additional Sheets If Necessary

2RP-3624