

Received 10/31/2016

NMOCD Artesia

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action**OPERATOR**☐ Initial Report ☒ Final Report

Name of Company: Dakota Resources Inc.	Contact: Chris Morphew
Address: 4912 N Midkiff Rd. Midland, TX 79705	Telephone No. 432-697-3420
Facility Name: Trigg Federal #001	Facility Type: SWD

Surface Owner: BLM	Mineral Owner: Federal	API No. 30-015-25006
--------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter L	Section 7	Township 21S	Range 28E	Feet from the 1980	North/South Line South	Feet from the 660	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	----------------

Latitude 32.493084 Longitude -104.132318

NATURE OF RELEASE

Type of Release: Mixed Fluids	Volume of Release: 40bbls	Volume Recovered: 0
Source of Release: Storage Tank	Date and Hour of Occurrence: 8/6/2013	Date and Hour of Discovery: 8/6/2013 9:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Randy Dade-NMOCD	
By Whom? LaWayne Day	Date and Hour: 8/6/2013 11:00am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

A storage tank within the bermed tank battery leaked resulting in the release of 40bbls of mixed fluids. Talon/LPE was contracted to perform soil sampling within the impacted area and draft a remediation work plan.

Describe Area Affected and Cleanup Action Taken.*

The release impacted the bermed tank battery, breached the berms and flowed southeast across the location for approximately 60-feet. No fluid left the location. Talon/LPE conducted soil sampling and developed scope of work that was approved by BLM and NMOCD. The remediation was carried out in accordance with the approved scope of work. All of the excavated soil was hauled to an NMOCD approved solid waste disposal facility. The excavation was backfilled with caliche and contoured to match the surrounding terrain following NMOCD and BLM permission to backfill the excavation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Chris Morphew	Approved by Environmental Specialist:	
Title: President/CEO	Approval Date: 11/7/2016	Expiration Date: N/A
E-mail Address: chrism@dakotares.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/28/2016 Phone: 432-697-3420	FINAL	

* Attach Additional Sheets If Necessary

2RP-1814